

BOSSWELD LT101 PLASMA TORCH PARTS

LT101

TYPE	PART NO.
Bossweld 6Mt Plasma Torch LT100	94.00157



CROWN
94.CV0014 Crown

NOZZLES
94.PC0109 Outer nozzle
94.PC0111 Outer nozzle

TIPS
94.PD0101-11 Tip
94.PD0101-14 Tip
94.PD0101-17 Tip
94.PD0101-30 Tip

ELECTRODE
94.PR0101 Electrode



CROWN
94.CV0012 Crown

GUIDE
94.CV0039 Guide



AIR DIFFUSER
94.PE0101 Diffuser



STAND OFF
94.CV0011 Stand off



GUIDE
94.CV0023 Guide



SHIELD CAP
94.PC0130 Shield cap



EXTENDED ELECTRODE
94.PR0116 Extended

EXTENDED TIP
94.PD0117-14 Tip
94.PD0117-17 Tip
94.PD0111-12 Tip



Central Adaptor